

# Hard Pipe Set Up with CO Monitor and 41 Series Filter

Compressor  
3/4" drop  
NPT Male Nipple




**Reducer**  
3/4" to 1" F/F



**1" Nipple**  
Threaded Both Ends

Monitor may connect to 1/4" NPT outlet or can connect to a tee off the gauge (connector kit included with monitor)

(For 41P6 - the sampling monitor will connect to one of the 3/8 NPT outlets or can connect to a tee off the gauge (connector kit included with monitor)



**41P2 & COHP (COHP41P2)**  
1" NPT Inlet  
1/4" NPT Outlet Female to Sampling Monitor  
3/8" NPT Outlet Female to worker

## 1/4" Industrial Interchange (Hansen Compatible)



**V15**  
3/8" Male NPT, 1/4" Female  
Industrial Interchange QD Coupler



**V17**  
1/4" Male Nipple  
(included in 4696)



**V13**  
Hose to Pipe Adaptor  
(included in 4696)



**4696**  
Starter Hose



**F30**  
1/4" Industrial Interchange Fitting

## 1/4" Snaptite



1/4" x 1/4" M/M  
Threaded Nipple



**V19**  
3/8" Male NPT  
1/4" Female QD Snaptite  
Coupler Outlet



**S19442**  
**S19443 (Brass)**  
1/4" Male Nipple  
Snaptite



**V12**  
Hose to Pipe  
Adaptor



**46915**  
Starter Hose



**F32**  
1/4" Snaptite Fitting



**20BT**  
Breathing Tube

**CC20 Series Hood**



## 1/4" Schrader



1/4" x 1/4" M/M  
Threaded Nipple



**V18**  
1/4" Female QD  
Schrader Outlet Coupler



**S19432**  
1/4" Male Nipple  
Schrader



**V12**  
Hose to Pipe  
Adaptor



**46915**  
Starter Hose



**F31**  
1/4" Schrader Fitting