

Bullard Type I hard hats and caps have been tested and found to be compliant to the requirements of the ANSI/ISEA Z89.1-2009 standard when worn with the shell turned backward.

To perform properly in this manner, the suspension must be reversed in the helmet, so that the headband is oriented normally to the wearer's head (i.e., with the brow pad against the forehead and the extended nape strap at the base of the skull). In this manner, only the shell of the helmet is backwards on the head.

This applies to Z89.1-2009 Type I hats and caps only (Bullard models C30, C33, C34, S51, S61, S62, S71, 911C AND 911H).

Type II helmets (Advent and Vector) should not be worn backward because of the lower rear edge of the shell and the asymmetrical pattern of protection offered by their more complex design.

If any of this is unclear, or if you have further questions, please feel free to call Bullard Customer Service at 877-BULLARD (285-5273).



Americas:
E.D. Bullard Company
1898 Safety Way
Cynthiana, KY 41031-9303
Toll free: 877-BULLARD (285-5273)
Tel: 859-234-6616
Fax: 859-234-8987
www.bullard.com

Europe:
Bullard GmbH
Lilienthalstrasse 12
53424 Remagen • Germany
Tel: +49-2642 999980
Fax: +49-2642 9999829
www.bullardextrem.com

Asia-Pacific:
Bullard Asia Pacific Pte. Ltd.
LHK Building
701, Sims Drive, #04-03
Singapore 387383
Tel: +65-6745-0556
Fax: +65-6745-5176
www.bullard.com



The Bullard three-rib design
is a registered trademark
of the E.D. Bullard Company.

